

Inspection Report

Report No.: XYDA-150320

Supplier: XY-GLOBAL

Inspection Date: 15th Apr, 2015

Inspector: Leo

Inspection only for: PO : XYDA-150320 Item No. XY31CY037	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY037	66000PCS	1% inspection	0pcs	No failure	55000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

