

Inspection Report

Report No.: XYCY-150303
Supplier: XY-GLOBAL

Inspection Date: 25th Mar, 2015
Inspector: Leo

Inspection only for: PO . XYCY-150303 Item No. XY31CY005	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY005	3000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Document Part No. REV. 01	Product Type XYCY-150303 XYCY-150303	Inspection Date 2015.03.25	Inspector Leo
Inspection Item XYCY-150303	Inspection Result PASS	Inspection Method 100%	Inspection Equipment Visual
Inspection Location XYCY-150303	Inspection Environment 25°C	Inspection Time 10:00-12:00	Inspection Status OK
Inspection Operator Leo	Inspection Supervisor Leo	Inspection Reviewer Leo	Inspection Approval Leo
Inspection Conclusion No defect found.	Inspection Summary No defect found.	Inspection Remarks No defect found.	Inspection Signature Leo

5. Product:

6. report

[illegible]