

Inspection Report

Report No.: XYCY-150318
Supplier : XY-GLOBAL

Inspection Date: 14th Apr, 2015
Inspector: Leo

Inspection only for: PO : XYCY-150318 Item No. XY31CY020	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY020	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report Form

Product Name: XY31CY020
Drawing No: XY31CY020
Inspection Date: 14/04/2015
Inspector: Leo

Inspection Result: PASS

Inspection Method: 100% inspection

Inspection Location: XY Electronics Technology Co., Ltd

Inspection Equipment: Vernier Caliper

Inspection Results:

Item	Spec	Actual	Result
1	Overall Dimension	10.0 ± 0.1	Pass
2	Inner Diameter	5.0 ± 0.1	Pass
3	Outer Diameter	12.0 ± 0.1	Pass
4	Length	15.0 ± 0.1	Pass
5	Weight	10.0 ± 0.1	Pass
6	Surface Finish	1.0 ± 0.1	Pass
7	Material	Aluminum	Pass
8	Heat Treatment	T6	Pass
9	Paint	Black	Pass
10	Assembly	Good	Pass
11	Function	Good	Pass
12	Reliability	Good	Pass
13	Stability	Good	Pass
14	Consistency	Good	Pass
15	Compliance	Good	Pass

Inspector: Leo
Date: 14/04/2015

5. Product:

6. report

[illegible]