

Inspection Report

Report No.: XYSK-140604
Supplier : XY-GLOBAL

Inspection Date: 2th July, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140604 Item No. XY31SY004	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY004	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

检验报告 / Inspection Report

客户名称 / Customer:	XY Electronics Technology Co., Ltd	检验日期 / Inspection Date:	2014.07.02
产品名称 / Product Name:	XY31SY004	检验地点 / Inspection Place:	XY Electronics Technology Co., Ltd
检验员 / Inspector:	Leo	检验结果 / Inspection Result:	PASS

检验内容 / Inspection Content: 1. 外观检查 (Appearance Check) 2. 尺寸检查 (Dimension Check) 3. 功能检查 (Function Check)

检验结论 / Conclusion: 1. 外观检查: 合格 (Pass) 2. 尺寸检查: 合格 (Pass) 3. 功能检查: 合格 (Pass)

检验日期 / Inspection Date: 2014.07.02

检验员 / Inspector: Leo

6. report

11

[illegible]

1. 1111111111CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 100000 ISO 100

2. □□□□□□□□□□□□

3.

4.

5. □□□□□

6.□□□□□□

7. □□□□□□□□□□□□□□□□

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
