

Inspection Report

Report No.: XYF-130829

Supplier : XY-GLOBAL

Inspection Date: 26th Sep, 2013

Inspector:LEO

Inspection only for: PO . XYF-130829 Item No. 800-20-450	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
800-20-450	20000Set	100% inspection	0pcs	No failure	20000Set

Appearance Inspection :

No failure.

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. inspection reports

[illegible]