

Inspection Report

Report No.: XYF-130814

Supplier : XY-GLOBAL


Inspection Date: 6th Sep-, 2013

Inspector: LEO

Inspection only for: PO . XYF-130814 Item No. screw	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
screw	10000Set	100% inspection	0pcs	No failure	10000Set

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

品名	CNC加工部品CNC加工
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	
数量	
単位	
納期	
備考	
価格	
公差	+/-0.01mm
表面処理	50μm研磨50μm研磨
検査方法	
梱包	
重量	
寸法	50mmx25mm
その他	
1.CNC加工	
2.	
AL6061 AL6065AL6063AL7075	
4.	
5.±0.01mm	
6.100mm	
7.	
8.25-30mm	
9.	
10.	
11.ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	