

Inspection Report

Report No.: XYF-130818

Supplier : XY-GLOBAL

Inspection Date: 10th Sep, 2013

Inspector: LEO

Inspection only for:	Inspection Result:
PO . XYF-130818 Item No. long screw	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
long screw	15000Set	100% inspection	0pcs	No failure	15000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

podmis									
Inspection Report									
Report No: XYF-130818									
Inspector: LEO									
Item No: long screw									
Quantity: 15000Set									
Sample Size: 100%									
Defect Found: 0pcs									
Defects Description: No failure									
Acceptable Q'ty: 15000Set									
Inspection Summary: The inspection sample plan is 100% inspection.									

6. inspection reports

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
	+/-0.01
	5050
	5025
1.CNC	
2.	
AL6061 AL6065AL6063AL7075	
4.	
5. ± 0.01	
6.100	
7.	
8.25-30	
9.	
10.	
11ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	