

Inspection Report

Report No.: XYSL-150717
Supplier : XY-GLOBAL

Inspection Date: 22nd Aug, 2015
Inspector: Leo

Inspection only for: PO . XYSL-150717 Item No. XY31XL037	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL037	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

[illegible]

Safety is our serious job for our worker and engineer team

