

## Inspection Report

Report No.: XYKB-140512

Inspection Date: 8<sup>th</sup> Jun, 2014

Supplier : XY-GLOBAL

Inspector: Leo

|                                                             |                                   |
|-------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO : XYKB-140512 Item No. XY72YM008 | <u>Inspection Result:</u><br>PASS |
|-------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY72YM008   | 6000PCS       | 1% inspection | 0pcs         | No failure          | 6000pcs         |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

### XY-GLOBAL 深圳市真朴电子科技有限公司

|                           |                   |                   |                 |                 |
|---------------------------|-------------------|-------------------|-----------------|-----------------|
| Inspection Report         | Product Name      | Inspection Date   | Inspector       | Page 5 of 5     |
| XY72YM008                 | XY72YM008         | 2014/06/08        | Leo             |                 |
| Inspection Method         | Inspection Result | Inspection Status | Inspection Date | Inspection Time |
| Visual Inspection         | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Inspection Item           | Inspection Result | Inspection Status | Inspection Date | Inspection Time |
| Dimensional Inspection    | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Material Inspection       | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Surface Inspection        | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Functionality Inspection  | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Assembly Inspection       | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Storage Inspection        | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Transportation Inspection | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Usage Inspection          | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Disposal Inspection       | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Recycling Inspection      | Pass              | Pass              | 2014/06/08      | 10:00:00        |
| Other Inspection          | Pass              | Pass              | 2014/06/08      | 10:00:00        |

6. Dimensions report:

