

Inspection Report

Report No.: XYAD-130808

Inspection Date: 6th Sep-, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for: PO . XYAD-130808 Item No. 7082014	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
7082014	3000PCS	100% inspection	0pcs	No failure	3000PCS

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product

[illegible]