

Inspection Report

Report No.: XYI-140317
Supplier : XY-GLOBAL

Inspection Date: 13th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYI-140317 Item No.142150	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142150	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary


The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Report:

	OEM
ADC12A380	
	CNC
	gague
	+/-0.01
	T / T 50T / T
	T / T 5020-25 NBSP
1.Name	
2.Process	
ADC12A380	
4.	
5.Tolerance±0.01	
6.100	
7.Specificationserice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
NBSP;	
ISO9001	
OEM	