

Inspection Report

Report No.: XYWD-140601

Inspection Date: 2nd July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO : XYWD-140601 Item No. XY31SY22	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY22	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd	
Inspection Report	Product Name: XY31SY22
Inspection Date: 2014-07-02	Inspection Time: 2014-07-02
Inspector: Leo	Inspector: Leo
Inspection Item: 1. Appearance 2. Dimension 3. Assembly	Inspection Result: PASS
Inspection Method: 1. Visual 2. Caliper 3. Assembly	Inspection Equipment: Caliper
Inspection Environment: 1. Temperature: 25°C 2. Humidity: 50%	Inspection Location: XY Electronics Technology Co., Ltd
Inspection Conclusion: 1. The product meets the requirements of the drawing. 2. The product is qualified for shipment.	Inspection Report No: XYWD-140601

5. Product:

6. report

[illegible]