

Inspection Report

Report No.: XYSK-140612
Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140612 Item No. XY31SY012	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY012	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Drawn	Checked	Reviewed	Inspected	Approved	Signature
Leo	Leo	Leo	Leo	Leo	Leo
Date	Date	Date	Date	Date	Date
2014.07.05	2014.07.05	2014.07.05	2014.07.05	2014.07.05	2014.07.05

Inspection Result: PASS

Inspection Method: 100% inspection

Inspection Item: XY31SY012

Inspection Result: 0 Defects

Inspection Summary: The inspection sample plan is 100% inspection.

6. report

11

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	
数量	
単位	
備考	
納入期	
価格	
納期	
品質	
保証	
梱包	
出荷	
検出	
検査	
不良	
返品	
廃棄	
その他	

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 100000 ISO 100

2. □□□□□□□□□□□□□□

3.

4.

5. □□□□□

6. □□□□□□

7. □□□□□□□□□□□□□□□□

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
