

Inspection Report

Report No.: XYNK-130813

Supplier : XY-GLOBAL

Inspection Date:10th Sep-, 2013

Inspector:LEO

Inspection only for: PO . XYNK-130813 Item No.132289	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
12289	2000Pcs	100% inspection	0pcs	No failure	2000Pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. Product:

[illegible]