

Inspection Report

Report No.: XYNK-130820

Supplier : XY-GLOBAL

Inspection Date:16th Sep-, 2013

Inspector:LEO

Inspection only for:	<u>Inspection Result:</u>
PO : XYNK-130820 Item No.1320087	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1320087	500PCS	100% inspection	0pcs	No failure	500pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	品名指定CNC部品品名指定CNC部品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様指定
数量	数量指定数量指定数量指定
単位	単位指定単位
公差	公差指定公差指定公差指定公差指定 公差
表面処理	表面処理指定表面処理指定表面処理指定表面処理指定
検査	検査指定
単位/個	+/-0.01mm
重量	重量50g重量指定重量指定50g重量
寸法	寸法指定寸法指定寸法指定寸法指定寸法指定
色	色指定色指定色指定色指定色指定
形状	形状
寸法	寸法50mm寸法25mm
単位	単位指定
1.品名指定CNC部品	
2.品名指定品名指定	
品名指定AL6061 AL6065AL6063AL7075	
4.品名指定品名指定品名指定 公差	
5.公差指定±0.01mm	
6.重量指定100g	
7.品名指定品名指定品名指定	
8.寸法指定25-30mm	
9.品名指定品名指定品名指定 品名指定品名指定	
10.品名指定品名指定品名指定	
11.品名指定ISO 9001	
品名指定	
1.10品名指定ISO部品	
2.品名指定品名指定	
3.品名指定品名指定	
4.品名指定品名指定	
5.品名指定	
6.品名指定	
7.品名指定品名指定	
品名指定	
品名指定品名指定品名指定	
品名指定品名指定	
品名指定品名指定ISO9001	
品名指定品名指定品名指定	
品名OEM品名指定	