

ADC12

Inspection Report

Report No.: XYS-130517
Supplier : XY-GLOBAL

Inspection Date: 15th Jun, 2013
Inspector: Leo

Inspection only for: PO . XYS-130517 Item No.XY-1000020	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1000020	5000PCS	5% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

[illegible]