

Inspection Report
Report No.: XYN-131107

Supplier : XY-GLOBAL





Inspection Date: 2th Dec-, 2013

Inspector:KEN

Inspection only for: PO . XYN-131107 Item No.XY-MST-023	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-023	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC
	AL6061 AL6065AL6063AL7075; SUS304SUS303SUS316
	CNC
	gague
	+/-0.01
	T / T 5050T / T
	T / T 5020-25 NBSP
1.Name CNC	
2.Process	
AL6061 AL6065AL6063AL7075	
4.	
5.Tolerance ±0.01	
6.100	
7.Specification serice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
&NBSP;	
ISO9001	