



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYN-131104
Supplier : XY-GLOBAL

Inspection Date: 1th Dec-, 2013
Inspector:KEN

Inspection only for: PO . XYN-131104 Item No.XY-MST-020	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-020	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.


Digital photo records :




1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC
	SUS304SUS316
	CNC
	gague
	+/-0.01
	T / T 50T / T
	T / T 5020-25 NBSP
1.Name CNC	
2.Process	
AL6061 AL6063AL7075	
4.	
5.Tolerance±0.01	
6.100	
7.Specificationserice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
110ISO	
2.	
3.kindlsavailable	
4.	
5.	
6.	
7.	
&NBSP;	
ISO9001	