

Inspection Report

Report No.: XYK-140620
Supplier : XY-GLOBAL

Inspection Date: 9th Aug-, 2013
Inspector: Alex

Inspection only for: PO . XYK-140620	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140620	1000PCS	3% inspection	0pcs	No failure	1000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary


The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. Product:

[illegible]