

Inspection Date: 15th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH013	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure . below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

[illegible]