

Inspection Date: 12th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH010	20000PCS	1% inspection	Opes	No failure	20000pcs

The inspection sample plan is 100% inspection.

A photograph of a pallet loaded with 20 cardboard boxes, secured with yellow straps. The boxes are arranged in a 4x5 grid on a wooden pallet. Each box has a diamond-shaped logo on its side. The pallet is in a warehouse setting with other equipment visible in the background.



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
	+/-0.01
	5050
	5025
1.CNC	
2.	
AL6061 AL6065AL6063AL7075	
4.	
5. ± 0.01	
6.100	
7.	
8.25-30	
9.	
10.	
11ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	