

SUS 440□□□



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130827

Supplier : XY-GLOBAL

Inspection Date: 30th Sep-, 2013

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYK-130827 Item No.4542310	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
4542310	100PCS	100% inspection	0pcs	No failure	100pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316
仕様	仕様
数量	数量&NBSP;単位
備考	備考
寸法	寸法
公差	公差
表面処理	表面処理gague
包装	包装
単位	+/-0.01mm
重量	T / T 50T / T
納入期	納入期
納期	納期
価格	20-25T / T 50
送料	送料
1.Name CNC加工品	
2.Process	
AL6061 AL6065AL6063AL7075	
4.	
5.Tolerance±0.01mm	
6.100mm	
7.Specificationserice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
&NBSP;	
ISO9001	