

Inspection Report

Report No.: XYDW-140626
Supplier : XY-GLOBAL

Inspection Date: 22th July, 2014
Inspector: Leo

Inspection only for: PO : XYDW-140626 Item No. XY33AH019	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH019	62000PCS	1% inspection	0pcs	No failure	62000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Order No.	Product Type	Inspection Date	Inspector
XYDW-140626	XY33AH019	2014.07.22	Leo
Part No.	Lot No.	Inspection Qty	Pass Qty
XY33AH019	2014072201	62000	62000
Inspection Result	Inspection Method	Inspection Standard	Inspection Equipment
Pass	Visual	100%	Visual
Inspection Item	Inspection Result	Inspection Standard	Inspection Equipment
Appearance	OK	100%	Visual
Dimension	OK	100%	Visual
Function	OK	100%	Visual
Material	OK	100%	Visual
Label	OK	100%	Visual
Storage	OK	100%	Visual
Transportation	OK	100%	Visual
Others	OK	100%	Visual
Inspection Summary	The inspection sample plan is 100% inspection.		
Inspector	Leo	Inspector	Leo
Inspector	Leo	Inspector	Leo

6. report

[illegible]