

Inspection Report

Report No.: XYDW-140629
Supplier : XY-GLOBAL

Inspection Date: 22nd July, 2014
Inspector: Leo

Inspection only for: PO : XYDW-140629 Item No. XY33AH021	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH021	90000PCS	1% inspection	0pcs	No failure	90000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report

Product Name	XY33AH021	Inspection Date	2014-07-22
Product No.	XY33AH021	Inspector	Leo
Product Qty	90000PCS	Product Status	OK
Product Description	XY33AH021	Product Location	XY33AH021

Inspection Result: PASS

Inspection Summary: The inspection sample plan is 100% inspection.

Inspector: Leo

5. Product:

6. report

[illegible]