

Inspection Report

Report No.: XYSK-140619
Supplier: XY-GLOBAL

Inspection Date: 10th July, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140619 Item No. XY31SY018	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY018	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :																																					
																																					
1. Packing	2. Product																																				
																																					
3. Product	4 Product																																				
	XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd <table><tr><td>Inspection Date</td><td>10/07/2014</td><td>Inspection Time</td><td>10:00 AM</td><td>Inspector</td><td>Leo</td></tr><tr><td>Product Name</td><td>XY31SY018</td><td>Product Code</td><td>XY31SY018</td><td>Product Qty</td><td>10000</td></tr><tr><td>Inspection Item</td><td>Appearance</td><td>Inspection Method</td><td>Visual</td><td>Inspection Result</td><td>PASS</td></tr><tr><td>Inspection Location</td><td>XY Electronics Technology Co., Ltd</td><td>Inspection Equipment</td><td>Visual</td><td>Inspection Environment</td><td>Normal</td></tr><tr><td>Inspection Operator</td><td>Leo</td><td>Inspection Supervisor</td><td>Leo</td><td>Inspection Date</td><td>10/07/2014</td></tr><tr><td>Inspection Result</td><td>PASS</td><td>Inspection Remarks</td><td colspan="3">No defect found.</td></tr></table>	Inspection Date	10/07/2014	Inspection Time	10:00 AM	Inspector	Leo	Product Name	XY31SY018	Product Code	XY31SY018	Product Qty	10000	Inspection Item	Appearance	Inspection Method	Visual	Inspection Result	PASS	Inspection Location	XY Electronics Technology Co., Ltd	Inspection Equipment	Visual	Inspection Environment	Normal	Inspection Operator	Leo	Inspection Supervisor	Leo	Inspection Date	10/07/2014	Inspection Result	PASS	Inspection Remarks	No defect found.		
Inspection Date	10/07/2014	Inspection Time	10:00 AM	Inspector	Leo																																
Product Name	XY31SY018	Product Code	XY31SY018	Product Qty	10000																																
Inspection Item	Appearance	Inspection Method	Visual	Inspection Result	PASS																																
Inspection Location	XY Electronics Technology Co., Ltd	Inspection Equipment	Visual	Inspection Environment	Normal																																
Inspection Operator	Leo	Inspection Supervisor	Leo	Inspection Date	10/07/2014																																
Inspection Result	PASS	Inspection Remarks	No defect found.																																		
5. Product:	6. report																																				

11

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	
数量	
単位	
備考	
納入期	
価格	
納期	
品質	
保証	
梱包	
出荷	
検出	
検査	
不良	
返品	
廃棄	
その他	

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 1000000 ISO

2.

3. □□□□□□□□□□□□□□

[illegible]

5.□□□□□

6. □□□□□□

7.

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ ISO9001

[illegible]

□□OEM□□□□□□