

Inspection Report

Report No.: XYDA-150306

Supplier : XY-GLOBAL

Inspection Date: 1st Apr, 2015

Inspector: Leo

Inspection only for:	Inspection Result:
PO : XYDA-150306 Item No. XY31CY025	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY025	23000PCS	1% inspection	0pcs	No failure	23000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Product



3. Product



4 Product



5. Product:



6. report

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
	+/-0.01mm
	50mm50mm
	50mm25mm
1.CNC	
2.	
AL6061 AL6065AL6063AL7075	
4.	
5. $\pm 0.01\text{ mm}$	
6.100mm	
7.	
8.25-30mm	
9.	
10.	
11ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	