

Inspection Report

Report No.: XYSK-140613

Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014

Inspector: Leo

Inspection only for: PO : XYSK-140613 Item No. XY31SY013	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY013	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

XY31SY013 Inspection Report

Product Name	XY31SY013	Inspection Date	2014.07.05
Product Type	XY31SY013	Inspector	Leo
Lot No.	XY31SY013	Quantity	12000
Inspection Item	XY31SY013	Inspection Result	PASS
Inspection Method	XY31SY013	Inspection Location	XY31SY013
Inspection Equipment	XY31SY013	Inspection Environment	XY31SY013
Inspection Result	XY31SY013	Inspection Conclusion	XY31SY013
Inspection Remarks	XY31SY013	Inspection Signature	XY31SY013

5. Product:

6. report

11

[illegible]

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

[illegible]

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 100000 ISO 100

2. □□□□□□□□□□□□

3.

4.

5. □□□□□

6.□□□□□□

7. □□□□□□□□□□□□□□□□

[illegible][illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
