

## Inspection Report

Report No.: XYWD-140622  
Supplier : XY-GLOBAL

Inspection Date: 20<sup>th</sup> July, 2014  
Inspector: Leo

|                                                            |                            |
|------------------------------------------------------------|----------------------------|
| Inspection only for:<br>PO : XYWD-140622 Item No. XY31SY39 | Inspection Result:<br>PASS |
|------------------------------------------------------------|----------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31SY39    | 30000PCS      | 1% inspection | 0pcs         | No failure          | 30000pcs        |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :



1. Packing

2. Product



3. Product

4 Product



**XY-GLOBAL** 深圳市真朴电子科技有限公司  
XY Electronics Technology Co., Ltd

|                                                      |                                    |                           |                                |
|------------------------------------------------------|------------------------------------|---------------------------|--------------------------------|
| Inspection Date: 2014.07.20                          | Product Name: XY31SY39             | Inspection Item: XY31SY39 | Inspector: Leo                 |
| Inspection Place: XY Electronics Technology Co., Ltd | Inspection Method: 100% inspection | Inspection Result: PASS   | Inspection Report: XYWD-140622 |

1. Inspection Purpose: To verify the quality of the product according to the inspection plan.

2. Inspection Method: 100% inspection.

3. Inspection Result: PASS.

4. Inspection Conclusion: The product quality is good, and the inspection results are in line with the requirements.

5. Inspection Report: XYWD-140622.

6. Inspection Date: 2014.07.20.

7. Inspector: Leo.

8. Approval: [Signature]

5. Product:

6. report

[illegible]