

Inspection Report

Report No.: XYFA-130805

Supplier : XY-GLOBAL

Inspection Date: 1st Sep., 2013

Inspector: LEO

Inspection only for: PO . XYFA-130805 Item No. 400-01-085	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-01-085	5000pcs	100% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

項目	
項目名	高精度CNC加工品高精度CNC品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様
用途	用途
加工	加工
公差	公差
表面処理	表面処理
検査	検査
包装	包装
納期	納期
価格	価格
お問い合わせ	お問い合わせ
1.高精度CNC加工	
2.高精度加工品	
項目名AL6061 AL6065AL6063AL7075	
4.高精度加工品	
5.公差±0.01mm	
6.表面処理	
7.検査	
8.包装	
9.納期	
10.価格	
11.お問い合わせ	
項目名	
1.10項目ISO	
2.項目	
3.項目	
4.項目	
5.項目	
6.項目	
7.項目	
項目名	
項目	
項目	
項目ISO9001	
項目	
項目OEM	