XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYDW-140621
Supplier : **XY-GLOBAL**

Inspection Date: 15th- July, 2014
Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYDW-140621 Item No. XY33AH014	**PASS**

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH014	**32000PCS**	1% inspection	0pcs	No failure	32000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co.,Ltd

6. report

□□□□	□□□□□□□□CNC□□□□□□□□□□□□□CNC□□
□□	□□□ AL6061 AL6065□AL6063□AL7075□SUS304□SUS303□SUS316□
□□	□□□□□□□□
□□□□	□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□
□□	□□□□□□□□□□
□□□□	□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□ □□□
□□□□	□□□□□□□□□□□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□□□□□□