

Inspection Report

Report No.: XYWD-140607

Inspection Date: 3th July, 2014

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for: PO : XYWD-140607 Item No. XY31SY27	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY27	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Customer: XYWD-140607 Product: XY31SY27 Inspection Date: 2014-07-03 Inspected By: Leo

PO: XYWD-140607 Lot Number: XY31SY27 Drawing Code: XY31SY27

Inspection Method: 100% Inspection Result: PASS

Inspector: Leo Date: 2014-07-03

Apparatus: 100% Result: PASS

Remarks: 1. The inspection was performed on 20000 pieces of XY31SY27 components. 2. The inspection result is PASS. 3. The inspection was performed by Leo on 2014-07-03.

5. Product:

6. report

[illegible]