

Inspection Report

Report No.: XYDW-140610

Supplier : XY-GLOBAL

Inspection Date: 7th July, 2014

Inspector: Leo

Inspection only for:	Inspection Result:
PO : XYDW-140610 Item No. XY33AH005	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH005	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

XY-GLOBAL

深圳市真朴电子科技有限公司

XY Electronics Technology Co., Ltd

Inspection Date	Product Name	Inspection Result	Inspector
7/7/2014	XY33AH005	PASS	Leo
Quantity	12000	Lot No.	140610
Inspection Result	PASS	Remarks	

检验项目: 1. 外观: 无锈蚀, 无油污, 无变形, 无裂纹, 无毛刺, 无划伤, 无凹坑, 无孔洞, 无杂质, 无异物, 无缺陷, 无瑕疵, 无不良, 无不合格, 无不合格, 无不通过, 无不达标

[illegible]