XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYCY-150309 **Inspection Date:** 3th Apr, 2015
Supplier : **XY-GLOBAL** **Inspector:** Leo

Inspection only for:	Inspection Result:
PO . XYCY-150309 Item No. XY31CY011	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY011	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

6. report

[illegible]	[illegible]CNC[illegible]CNC[illegible]
[illegible]	[illegible] AL6061 AL6065[illegible]AL6063[illegible]AL7075[illegible]SUS304[illegible]SUS303[illegible]SUS316[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible] [illegible]
[illegible]	[illegible] [illegible]
[illegible]	[illegible]
[illegible]/[illegible]	+/-0.01[illegible]
[illegible]	[illegible]50[illegible]50[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]50[illegible]25[illegible]
[illegible]	[illegible]

1.[illegible]CNC[illegible]

2.[illegible]

[illegible]AL6061 AL6065[illegible]AL6063[illegible]AL7075[illegible]

4.[illegible] [illegible]

5.[illegible]±0.01[illegible]

6.[illegible]100[illegible]

7.[illegible]

8.[illegible]25-30[illegible]

9.[illegible] [illegible]

10.[illegible]

11[illegible]ISO 9001

[illegible]

1.10[illegible]ISO[illegible]

2.[illegible]

3.[illegible]

4.[illegible]

5.[illegible]

6.[illegible]

7.[illegible]

[illegible]

[illegible]

[illegible]

[illegible]ISO9001

[illegible]

[illegible]OEM[illegible]