

Inspection Report

Report No.: XYD-140503
Supplier : XY-GLOBAL

Inspection Date: 5th Jun, 2014
Inspector: Leo

Inspection only for: PO : XYD-140503 Item No.XY-140223	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140223	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:



7. Product:

A detailed inspection report table with multiple columns and rows, containing various data points and signatures. The table is titled 'pocdmis' and includes fields for 'Inspection Date', 'Inspector', and 'Product Name'.

8. Report:

[illegible]