

Inspection Report

Report No.: XYN-140514
Supplier : XY-GLOBAL

Inspection Date: 9th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYN-140514 Item No.XY-140330	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140330	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. Report:

品名	高精度加工品OEM加工品
品番	ADC12 A380
品名	高精度加工品
品名	高精度加工品
品名	CNC加工品
品名	高精度加工品gague
品名	高精度加工品
品名	+/-0.01
品名	T / T 50 T / T
品名	高精度加工品
品名	高精度加工品
品名	高精度加工品
品名	T / T 50 20-25 NBSP
品名	高精度加工品
1.Name	高精度加工品
2.Process	高精度加工品
	高精度加工品ADC12 A380
4.	高精度加工品
5.Tolerance	高精度加工品±0.01
6.	高精度加工品100
7.Specification	高精度加工品serice
8.	高精度加工品25-30
9.	高精度加工品accessoried
10.	高精度加工品Austrial
11&NBSP;	高精度加工品ISO 9001
高精度加工品	
1	高精度加工品ISO
2.	高精度加工品
3.	高精度加工品kindls available
4.	高精度加工品
5.	高精度加工品
6.	高精度加工品
7.	高精度加工品
高精度加工品	
	高精度加工品NBSP;高精度加工品
	高精度加工品
	高精度加工品ISO9001
	高精度加工品
	高精度加工品OEM