

Inspection Report

Report No.: XYK-140517
Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140517 Item No.XY-141708	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-141708	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product




3. Product



4 Product



5. Product:



6. Report:

00000	0000 00000000000000000000 00000000OEM0000000000 0000
00	0 ADC120A3800
00	0 000000
00000	0 000000000000000000000000 00000
00	0 0000000000
0000	00 0000000000000000 000000000000000000
0000	00 00000000gague000000000000 00000000000000000000 000000000000000000000000 0
00000	00
00/00	+/-0.0100
00	T / T 5000000000500T / T00000000
00000	00 000000000000000000 00000000000000000000
00	000 00000000000000000000 000000000000000000
00	000 00
00	20-25&NBSP;0 T / T 50000000
0000	00 000000
1.Name000000000000	
2.Process0 000000000000	
0000000000ADC120A3800	
4.0000000000000000000000 00000	
5.Tolerance0000±0.0100	
6.000000100000	
7.Specification0000serice000000000000	
8000000025-300000000000	
90000000000000000000 00accessoried0000000000	
10000000000000000000Austrial000000	
11&NBSP;0000ISO 9001	
00000000	
100100000000ISO00	
2000000000	
300000000000kindls0available	
4000000000000000	
50000000	
60000000	
7000000000000000	
00000000	
00000000&NBSP;00000000000 00	
0000000000000000	
000000000000ISO9001	
000000000000000000 00	
0000000000OEM0000	