

Inspection Date: 19th Aug, 2015
Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYSL-150712 Item No. XY31XL032	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL032	32000PCS	1% inspection	Opes	No failure	32000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. report

[illegible]

Safety is our serious job for our worker and engineer team

