



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-131022
Supplier : XY-GLOBAL

Inspection Date: 18th Nov-, 2013
Inspector: ALEX

Inspection only for: PO . XYK-131022 Item No.XY-CT-D-085	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-085	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

品名	铝合金 CNC 加工件
规格	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
数量	10000 件
用途	工业机械零件
材质	铝合金
表面处理	CNC 加工
公差	±0.01mm
包装	纸箱
交货期	10 天
备注	
1.Name	铝合金 CNC 加工件
2.Process	CNC 加工
3.	AL6061 AL6065 AL6063 AL7075
4.	工业机械零件
5.Tolerance	±0.01mm
6.	10000 件
7.Specification	serice
8.	25-30 天
9.	accessoried
10.	Austrial
11.&NBSP;	ISO 9001
品名	
1.	10 天
2.	工业机械零件
3.	kindls available
4.	工业机械零件
5.	工业机械零件
6.	工业机械零件
7.	工业机械零件
品名	
规格	&NBSP;
数量	10000 件
用途	工业机械零件
材质	铝合金
表面处理	CNC 加工
公差	±0.01mm
包装	纸箱
交货期	10 天