

Inspection Report

Report No.: XYWD-140627

Supplier : XY-GLOBAL

Inspection Date: 25th- July, 2014

Inspector: Leo

Inspection only for: PO . XYWD-140627 Item No. XY31SY44	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY44	30000PCS	1% inspection	Opes	No failure	30000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure	
------------	--

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. report

[illegible]