

Inspection Report

Report No.: XYS-131110
Supplier : XY-GLOBAL

Inspection Date: 25th Nov., 2013
Inspector: LEO

Inspection only for: PO : XYS-131110 Item No. screw bolt kit	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
screw bolt kit	1000PCS	50PCS inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316
仕様	標準仕様
数量	個単位
単位	個単位
寸法	図面参照
公差	+/-0.01mm
表面処理	亜光仕上げ
検査方法	目視・測定器による検査
梱包方法	ダンボール箱入り
納期	受注後約1週間
備考	