

Inspection Report

Report No.: XYWD-140625
Supplier : XY-GLOBAL

Inspection Date: 20th July, 2014
Inspector: Leo

Inspection only for: PO . XYWD-140625 Item No. XY31SY42	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY42	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

										
1. Packing 	2. Product 									
3. Product 	4 Product XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd <table border="1"> <tr> <td>Drawn by: JEN JIA JIA</td> <td>Checked by: Leo</td> <td>Inspection Date: 2014.7.20</td> </tr> <tr> <td>Part Name: XY31SY42</td> <td>Part No: XY31SY42</td> <td>Quantity: 50000</td> </tr> <tr> <td>Material: Brass</td> <td>Surface: Polished</td> <td>Delivery Date: 2014.7.25</td> </tr> </table> Inspection Result: PASS Inspector: Leo Signature: [Signature] Date: 2014.7.20	Drawn by: JEN JIA JIA	Checked by: Leo	Inspection Date: 2014.7.20	Part Name: XY31SY42	Part No: XY31SY42	Quantity: 50000	Material: Brass	Surface: Polished	Delivery Date: 2014.7.25
Drawn by: JEN JIA JIA	Checked by: Leo	Inspection Date: 2014.7.20								
Part Name: XY31SY42	Part No: XY31SY42	Quantity: 50000								
Material: Brass	Surface: Polished	Delivery Date: 2014.7.25								
5. Product:	6. report									

[illegible]