

Inspection Report

Report No.: XYAN-150412

Supplier : XY-GLOBAL


Inspection Date: 15th May-, 2015

Inspector: LEO

Inspection only for:	Inspection Result:
PO : XYAN-150412 Item No. XY21ZC079	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC079	9000pcs	7% inspection	0pcs	No failure	9000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	汎用部品CNC加工品汎用部品CNC加工品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様
数量	数量
単位	単位
公差	公差
表面処理	表面処理
検査	検査
納期	納期
価格	価格
備考	備考
1.汎用部品CNC加工品	
2.汎用部品CNC加工品	
汎用部品AL6061 AL6065AL6063AL7075	
4.汎用部品CNC加工品 仕様	
5.汎用部品±0.01mm	
6.汎用部品100mm	
7.汎用部品CNC加工品	
8.汎用部品25-30mm	
9.汎用部品CNC加工品 汎用部品CNC加工品	
10.汎用部品CNC加工品	
11汎用部品ISO 9001	
汎用部品	
1.10汎用部品ISO加工	
2.汎用部品CNC加工品	
3.汎用部品CNC加工品	
4.汎用部品CNC加工品	
5.汎用部品	
6.汎用部品	
7.汎用部品CNC加工品	
汎用部品	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用部品ISO9001	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用OEM加工品	

Safety is our serious job for our worker and engineer team

