

Inspection Report

Report No.: XYDA-140502
Supplier : XY-GLOBAL

Inspection Date: 1st Jun, 2014
Inspector: Leo

Inspection only for: PO . XYDA-140502 Item No.140589	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140589	14000PCS	1% inspection	0pcs	No failure	14000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product:

品名	铝合金压铸件OEM加工
规格	ADC12/A380
数量	10000个
用途	汽车零部件
材料	铝合金
工艺	CNC加工
表面处理	阳极氧化
交货期	15天
MOQ	1000个
公差	+/-0.01mm
包装	T / T 50% 50% T / T ; 100%
备注	
其他要求	
付款方式	T / T 50% 50% 20-25天
联系人	王经理
1.Name: 铝合金OEM加工	
2.Process: CNC加工	
3.规格: ADC12/A380	
4.数量: 10000个	
5.Tolerance: +/-0.01mm	
6.Quality: 100%	
7.Specification: OEM加工	
8.交期: 25-30天	
9.表面处理: accessoried	
10.包装: Austrial	
11.标准: ISO 9001	
1. 10000个ISO	
2. 10000个	
3. sureface kinds available	
4. 10000个	
5. 10000个	
6. 10000个	
7. 10000个	
10000个	
10000个	
10000个	
10000个ISO9001	
10000个	
10000个OEM	