

Inspection Report

Report No.: XYAN-150314
Supplier : XY-GLOBAL

Inspection Date: 16th Apr., 2015
Inspector: LEO

Inspection only for: PO : XYBA-150314 Item No. XY21ZC101	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC101	12000pcs	7% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

XY-21ZC101									
Q	12000	12000	12000	12000	12000	12000	12000	12000	12000
1	12000	12000	12000	12000	12000	12000	12000	12000	12000
2	12000	12000	12000	12000	12000	12000	12000	12000	12000
3	12000	12000	12000	12000	12000	12000	12000	12000	12000
4	12000	12000	12000	12000	12000	12000	12000	12000	12000
5	12000	12000	12000	12000	12000	12000	12000	12000	12000
6	12000	12000	12000	12000	12000	12000	12000	12000	12000
7	12000	12000	12000	12000	12000	12000	12000	12000	12000
8	12000	12000	12000	12000	12000	12000	12000	12000	12000
9	12000	12000	12000	12000	12000	12000	12000	12000	12000
10	12000	12000	12000	12000	12000	12000	12000	12000	12000
11	12000	12000	12000	12000	12000	12000	12000	12000	12000
12	12000	12000	12000	12000	12000	12000	12000	12000	12000
13	12000	12000	12000	12000	12000	12000	12000	12000	12000
14	12000	12000	12000	12000	12000	12000	12000	12000	12000
15	12000	12000	12000	12000	12000	12000	12000	12000	12000
16	12000	12000	12000	12000	12000	12000	12000	12000	12000
17	12000	12000	12000	12000	12000	12000	12000	12000	12000
18	12000	12000	12000	12000	12000	12000	12000	12000	12000
19	12000	12000	12000	12000	12000	12000	12000	12000	12000
20	12000	12000	12000	12000	12000	12000	12000	12000	12000
21	12000	12000	12000	12000	12000	12000	12000	12000	12000
22	12000	12000	12000	12000	12000	12000	12000	12000	12000
23	12000	12000	12000	12000	12000	12000	12000	12000	12000
24	12000	12000	12000	12000	12000	12000	12000	12000	12000
25	12000	12000	12000	12000	12000	12000	12000	12000	12000
26	12000	12000	12000	12000	12000	12000	12000	12000	12000
27	12000	12000	12000	12000	12000	12000	12000	12000	12000
28	12000	12000	12000	12000	12000	12000	12000	12000	12000
29	12000	12000	12000	12000	12000	12000	12000	12000	12000
30	12000	12000	12000	12000	12000	12000	12000	12000	12000
31	12000	12000	12000	12000	12000	12000	12000	12000	12000
32	12000	12000	12000	12000	12000	12000	12000	12000	12000
33	12000	12000	12000	12000	12000	12000	12000	12000	12000
34	12000	12000	12000	12000	12000	12000	12000	12000	12000
35	12000	12000	12000	12000	12000	12000	12000	12000	12000
36	12000	12000	12000	12000	12000	12000	12000	12000	12000
37	12000	12000	12000	12000	12000	12000	12000	12000	12000
38	12000	12000	12000	12000	12000	12000	12000	12000	12000
39	12000	12000	12000	12000	12000	12000	12000	12000	12000
40	12000	12000	12000	12000	12000	12000	12000	12000	12000
41	12000	12000	12000	12000	12000	12000	12000	12000	12000
42	12000	12000	12000	12000	12000	12000	12000	12000	12000
43	12000	12000	12000	12000	12000	12000	12000	12000	12000
44	12000	12000	12000	12000	12000	12000	12000	12000	12000
45	12000	12000	12000	12000	12000	12000	12000	12000	12000
46	12000	12000	12000	12000	12000	12000	12000	12000	12000
47	12000	12000	12000	12000	12000	12000	12000	12000	12000
48	12000	12000	12000	12000	12000	12000	12000	12000	12000
49	12000	12000	12000	12000	12000	12000	12000	12000	12000
50	12000	12000	12000	12000	12000	12000	12000	12000	12000

6. Inspection report:

[illegible]

Safety is our serious job for our worker and engineer team

