

Inspection Report

Report No.: XYS-130723
Supplier: XY-GLOBAL

Inspection Date: 12th Jun-, 2014
Inspector: LEO

Inspection only for: PO : XYS-130723 Item No. Aluminum cylinder units	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Aluminum cylinder units	100PCS	50pcs inspection	0pcs	No failure	100pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	CNC加工品CNC加工品
材料	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316
仕様	品名
数量	品名&NBSP;品名
単位	個
寸法	品名
公差	品名
表面処理	品名
検査方法	品名
納入期	品名
梱包	品名
備考	品名
1.Name	cnc加工品
2.Process	品名
3.	品名AL6061 AL6065AL6063AL7075
4.	品名
5.Tolerance	品名±0.01
6.	品名100
7.Specification	品名serice
8.	品名25-30
9.	品名accessoried
10.	品名Austrial
11&NBSP;	品名ISO 9001
品名	
1	品名10ISO
2	品名
3	品名kindlsavailable
4	品名
5	品名
6	品名
7	品名
品名	
品名&NBSP;	品名
品名	
品名ISO9001	
品名	
品名	