

Inspection Report

Report No.: XYDA-150310
Supplier : XY-GLOBAL

Inspection Date: 4th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYDA-150310 Item No. XY31CY028	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY028	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Form No. XYDA-150310	Product Name XY31CY028	Inspection Date 2015-04-04	Inspector Leo
Inspection Result: PASS			
Inspection Summary: No failure			
Inspection Details: 100% inspection			
Inspection Conclusion: The inspection sample plan is 100% inspection.			

6. report

[illegible]