

Inspection Report

Report No.: XYAN-150319

Supplier : XY-GLOBAL

Inspection Date: 25th Apr-, 2015

Inspector:LEO

Inspection only for:	Inspection Result:
PO . XYBA-150319 Item No. XY21ZC106	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC106	12000pcs	7% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

[illegible]

1000

6. Inspection report:

[illegible]

Safety is our serious job for our worker and engineer team

