

Inspection Report



Report No.: XYK-131011
Supplier : XY-GLOBAL

Inspection Date: 29th Oct., 2013
Inspector: LEO

Inspection only for: PO . XYK-131011 Item No. adapting piece	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
adapting piece	3000SET	5% inspection	0pcs	No failure	3000SET

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 5% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	鋼板 CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075&NBSP; SUS304SUS303SUS316
厚さ	1mm
寸法	100mm x 100mm
表面処理	研磨仕上げ
公差	CNC加工品±0.01mm
検査方法	目視検査、ゲージ検査、重量測定
梱包単位	1箱
納期	+/-0.01日
備考	T / T 50%前払い50%T / T後払い
お問い合わせ先	株式会社 〇〇〇〇〇〇〇〇〇〇〇 〇〇〇〇〇〇〇〇〇〇〇〇 〇
住所	〒100-0001 東京都千代田区〇〇〇〇 〇〇〇
TEL	03-XXXX-XXXX
FAX	T / T 50%前払い20-25 NBSP
Eメール	info@o-o-o.co.jp
1.Name 鋼板cnc加工品	
2.Process 機械加工	
材料AL6061 AL6065AL6063AL7075	
4.品質保証書発行可能 〇	
5.Tolerance ±0.01mm	
6.ロット数100個	
7.Specification 仕様service 標準仕様	
8.価格帯25-30万円程度	
9.付属品有無〇〇〇〇〇〇〇〇〇〇 〇〇accessoried 〇〇〇〇〇〇〇〇	
10.認証取得状況Austrial 〇〇〇〇	
11&NBSP;規格ISO 9001	
〇〇 〇〇	
1.10年間のISO	
2.品質保証	
3.品質管理kindls available	
4.品質保証書	
5.品質保証	
6.品質保証	
7.品質保証書	
〇〇 〇〇	
品質保証&NBSP;品質保証書	
品質保証書	
品質保証書ISO9001	
品質保証書	
品質保証書	