

Inspection Report

Report No.: XYS-130823
Supplier : XY-GLOBAL

Inspection Date: 12th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYS-130823 Item No. Drive Shaft	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Drive Shaft	10000PCS	10% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 50pcs inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

品名	鋼板 CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075&NBSP; SUS304SUS303SUS316
厚さ	1mm
寸法	1000mm x 1000mm
表面処理	研磨仕上げ
公差	CNC加工品±0.01mm
検査方法	目視検査、ゲージ検査、硬度試験、引張試験
梱包方法	木箱包装
単位	枚
公差	+/-0.01mm
仕様	T / T 50T / T 50T / T 50
備考	※ご注文の際は、必ず仕様書をご確認ください。
品質保証	品質保証書発行可能
納期	約1週間
送料	T / T 5020-25 NBSP
お問い合わせ先	お問い合わせ先
1.Name CNC加工品	
2.Process 切削加工	
3.Material AL6061 AL6065AL6063AL7075	
4.Surface Treatment 研磨仕上げ	
5.Tolerance ±0.01mm	
6.Quantity 100枚	
7.Specification serice	
8.Length 25-30cm	
9.Accessories accessoried	
10.Certification Austria	
11.&NBSP; ISO 9001	
お問い合わせ先	
1. 10mm ISO	
2. 10mm	
3. kinds available	
4. 10mm	
5. 10mm	
6. 10mm	
7. 10mm	
お問い合わせ先	
&NBSP;	
お問い合わせ先	
ISO9001	
お問い合わせ先	
お問い合わせ先	