

Inspection Report

Report No.: XYSL-150605
Supplier : XY-GLOBAL

Inspection Date: 10th July, 2015
Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYSL-150605 Item No. XY31XL003	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL003	42000PCS	1% inspection	0pcs	No failure	42000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	 XY31XL003
5. Product:	6. report

項目	項目名CNC加工品CNC加工品
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様書
数量	数量指定可能
単位	個単位
納期	納期目安約2週間
送料	送料別注
備考	備考欄
公差	+/-0.01mm
重量	重量約50g
色	色指定可能
表面処理	表面処理可能
検査	検査可能
保証	保証期間5年
お問い合わせ	お問い合わせ先
1. CNC加工品	
2. 加工品	
AL6061 AL6065AL6063AL7075	
4. 仕様書	
5. 公差±0.01mm	
6. 重量100g	
7. 色指定可能	
8. 表面処理25-30μm	
9. 検査可能	
10. 保証期間5年	
11. ISO 9001	
お問い合わせ	
1.10. ISO	
2. 加工品	
3. 仕様書	
4. 重量	
5. 色指定可能	
6. 表面処理	
7. 検査可能	
お問い合わせ	
お問い合わせ先	
お問い合わせ先	
ISO9001	
お問い合わせ先	
OEM加工品	

Safety is our serious job for our worker and engineer team

